



Bridge No	Bridge Name	Location	Works Type
6.197	North Common Bridge	RU41 North Common Road	Structure Replacement
2.001	Fish Pond	A638, Great North Road, Bawtry	Maintenance Works
5.209	Thorpe Lane Bridge	C317, Thorpe Lane, Thorpe in Balne	Structure Replacement
5.208	Rockley Lane Culvert	C317, Rockley Lane, Owston	Maintenance Works
3.093	Greys Footbridge Repainting	Denaby Main	Maintenance Works
R5601.01	Balby Road Retaining Wall	A630, High Road, Balby	Maintenance Works
3.101	St George's Bridge	A19, St George's Way	Maintenance Works
R4799.24	Mexborough Police Station Wall	Mexborough	Maintenance Works
3.075	Balby New Bridge	A630, Balby Road, Balby	Structural Inspection
3.005	Bentley Flood Arches	A19, Bentley Road, Bentley	Maintenance Works
R4808.11	Hooton Pagnell Retaining Wall	Hooton Pagnell	Maintenance Works
7.187	Estate Dock Thorne	Thorne	Maintenance Works
7.141	Engine Dyke Footbridge	Thorpe in Balne Footpath 08	Structure Replacement
5.196	Clay Bridge	C308, Kirk Lane, Sykehouse	Maintenance Works
6.074	Adwick Lane Culvert	U157 Adwick Lane, Adwick	Structure Replacement
R5703.13	Hall Cross Retaining Wall	Thorne Road	Maintenance Works
4.182	Cliff Spring Drain Culvert	B6422, Brodsworth	Structure Replacement
6.155	Willow Bridge Culvert	U16, Trumflett	Maintenance Works